



Moisture Calibration on 60 Series Combine


1. Press Main Menu Button.




2. Press "Original GreenStar Monitor" Button.



3. Press "Setup" Button.



4. Press "A" Button for Harvest Monitor.



5. Press "E" Button for Moisture.

1	2	SETUP Harv Mon PAGE 1	
3	4	Farm: Setup in Harvest Doc	A
5	6	Field: Setup in Harvest Doc	B
7	8	Crop: Setup in Harvest Doc	
9	0	Header Type: Corn Head →	C
.	CLR	Yield Calibration →	D
PAGE		Moisture →	E
SETUP		Record Stop Height Save	F
INFO		50.0%	
RUN		SETUP Setup ↶	G


4:37 pm

6. Press "D" Button for Moisture Calibration.


1	2	SETUP Moisture	
3	4	Moisture Correction 0.8 →	A
5	6	Moisture Alarm: ON →	B
7	8		
9	0	Moisture Curve →	C
.	CLR	Moisture Calibration →	D
PAGE		Samling Rate per Minute →	E
SETUP		SAMPLING DISABLED	F
INFO			
RUN		SETUP Harvest Mon ↶	G

4:38 pm


7. Make sure that engine is off and grain tank is empty. Then press "C" Button for Continue.



8. "Calibrating" will appear on the screen.



9. "Calibration Complete" will appear on the screen next.



10. Press Home Button and Harvest.

